



OX App Suite Engineering Services Plugins
Release Notes for Release 1.6.3
2021-04-30

Copyright notice

©2021 by OX Software GmbH. All rights reserved. Open-Xchange and the Open-Xchange logo are trademarks or registered trademarks of OX Software GmbH. All other company and/or product names may be trademarks or registered trademarks of their owners. Information contained in this document is subject to change without notice.

Contents

1 Shipped Product and Version	2
2 Bugs fixed with this Release	2
3 Tests	2
4 Fixed Bugs	2

1 Shipped Product and Version

OX App Suite Engineering Services Plugins 1.6.3

Find more information about product versions and releases at http://oxpedia.org/wiki/index.php?title=AppSuite:Versioning_and_Numbering and <http://documentation.open-xchange.com/>.

2 Bugs fixed with this Release

This section provides a summary of bug fixes and changes that have been applied subsequently to shipping Release 1.6.3. Some of the announced bug fixes may have already been fixed at the existing code-base via Patch Releases.

PLG-191 Change propagation status display logic

Status: Done

Root Cause Description:

Customer needed logic change

Solution Description:

Made change

Resolution: Verified

Severity: 3

Verified with Builds: plugins-1.6.3-rev7

Labels: L3

Affected Packages: open-xchange-appsuite-mx-checker

3 Tests

Not all defects that got resolved could be reproduced within the lab. Therefore, we advise guided and close monitoring of the reported defect when deploying to a staging or production environment. Defects which have not been fully verified, are marked as such.

To avoid side effects, the shipped packages have gone through automated regression test on both, a Continuous Integration System and a dedicated server set-up for system and integration testing. All changes have been checked for potential side-effects and effect on behavior. Unless explicitly stated within this document, we do not expect any side-effects.

4 Fixed Bugs

[PLG-191](#),